

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 747 Const Calendar Day: 205 Date: 26-Dec-2012 Wednesday Inspector Name: Bruce, Matt Title: Transportation Engineer

Inspection Type: Continuous

Shift Hours: 07:00 am 03:30 pm Break: 00:30 Over Time:

Federal ID: Location:

Reviewer: Schmitt, Alex Approved Date: Status: Submit

Weather

Temperature 7 AM 50 - 60 **12 PM** 50 - 60 **4PM** 50 - 60

Precipitation 0.07" Condition Light rain in AM to mostly overcast and windy

Working Day

If no, explain:

04-0120F4	Bid Item: (067 C-PWS-HDR.067	Install Har	nd Rope				
AMERICAN BRII	DGE/FLUOR, A	JV						
Labor								
Trade	Class	Name	RT Hrs	OT Hrs	DT Hrs	Total	Remarks	Dispute
Contractor: AMERICAN BRIDGE/FLUOR, A JV								
Ironworker	APP	RYAN NASH	8.00	0.00	0.00	8.00		
Ironworker	APP	SERGIO GARCIA	8.00	0.00	0.00	8.00		
Ironworker	APP	MARIO MARQUEZ	8.00	0.00	0.00	8.00		
Ironworker	JNM	CARLOS BUSTAMANTE	8.00	0.00	0.00	8.00		
Ironworker	APP	JAVIER GARCIA	8.00	0.00	0.00	8.00		
Ironworker	JNM	RIGOVERTO GARCIA	8.00	0.00	0.00	8.00		
Ironworker	FOR	OBRA PAULK	8.00	0.00	0.00	8.00		
Diary: Work description. 067 C-PWS-HDR.067								Dispute
- ABF ironworkers attempted to install all of the inboard electrical pullbox post supports on the North Sidespan. None of the post type supports were installed due to the messenger cable set higher than the post length to connect with the cable band, see photos below for more details. Once it was discovered the post length was too short, part of the crew went to the South Sidespan and the other mobilized the electrical pullbox post supports down onto the OBG for modification.								
The rest of the day was spent erecting the South Sidespan outboard electrical pullboxes (post support type). The operation commenced from cable band 10S progressing up to cable band 30S. It should be noted that the only electrical pullbox post support not installed on this span was at cable band 26S. At this location the ironworkers couldn't screw in the top post bolt. For this tapped hole bolted connection, Loctite is applied either in the hole or on the bolt then the bolt is snug tight.								

Attachment



Page 1 of 2

Run date 21-Nov-14

Time

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

10:50 PM

Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name Bruce, Matt Diary #: 747 Date: 26-Dec-2012 Wednesday



ABF ironworkers connecting an electrical pullbox support on the outboard side of cable band 22S.



Inboard electrical pullbox post support which didn't have sufficient length to connect to cable band 36N.



Inboard electrical pullbox support (non post) connected to cable band $24\mbox{N}.$